103 The Street, Adisham, Canterbury, Kent,

CT33JP, England.

07568487894

castlecapers_bouncycastlerepairs@yahoo.com

www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No	Size		Туре		Make
CC0007	4m L x 3.8m W x 3m H		12x12 Seaworld Ca	astle	Airquee
Name and address of owr	ner	1 st Choice Infl			flatables
Manufacture date Place of in		nspection		Name of inspector	
2017		1 st Choice Inflatables		Louise Reade	

Anchorage	Structure	Totally enclosed	
How Many/type	Seams & stitching	Exits	
Accessories	Blower length	Exit markings	
Blower	Inside wall height	Independent support	
Inlet, outlet mesh	Fall off height	Deflation	
Cable and socket	Step/ramp	Emergency lighting	
Impeller & flap	Entrapment	Slides	
1.5hp	Trough depth	Platform height	
PAT test	Grounding	Platform wall	
Material	Sharp angles	1 st M wall	
Fabric FR/strength	Stability	Slope remainder	
Zips	Pressure	Climb	
Thread	deflation	Run out	
Rope	Air loss	End	
Netting	Markings	Slip sheet	
Windows	Identifications	Climb sheet	
Artwork	Walls & towers	Run out length	

<u>below</u>

How many users to height

1 M = 6 1.2 M = 4 1.5 M = 3 1.8 M = 2

Risk assessment	Notes
This inflatable is a safety bed on which the designated activity	Max height = 1.8m
only should take place. Designated entrance and exit areas should be adhered to at all times. This safety certificate is for the	Max users at this height = 2
inflatable only.	

I certify that the above equipment has been tested to BSEN 14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection: 19.02.25

Expiry date: 19.02.26

