103 The Street, Adisham, Canterbury, Kent,

CT33JP, England.

07568487894

castlecapers_bouncycastlerepairs@yahoo.com

www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No	Size		Туре		Make
CC0047	6m L x 2.9m W x 3.1m H		Jungle slide		Air Inflatables
Name and address of own	owner		1 st choice inflatables		
Manufacture date		Place of inspection		Name of inspector	
2013		1 st choice inflatables		Louise Reade	

Structure	Totally enclosed
Seams & stitching	Exits
Blower length	Exit markings
Inside wall height	Independent support
Fall off height	Deflation
Step/ramp	Emergency lighting
Entrapment	Slides
Trough depth	Platform height
Grounding	Platform wall
Sharp angles	1 st M wall
Stability	Slope remainder
Pressure	Climb
deflation	Run out
Air loss	End
Markings	Slip sheet
Identifications	Climb sheet
Walls & towers	Run out length
t have been inspected and f	ound satisfactory unless liste
	Seams & stitching Blower length Inside wall height Fall off height Step/ramp Entrapment Trough depth Grounding Sharp angles Stability Pressure deflation Air loss Markings Identifications

<u>below</u>

How many users to height

1 M = 3	1.2 M = 3	1.5 M = 3	1.8 M = 0
---------	-----------	-----------	-----------

Risk assessment	Notes	
Designated entrance and exit areas should be adhered to at all	Max height = 1.5m	
times. This safety certificate is for the inflatable only.	Max users at this height = 3	

I certify that the above equipment has been tested to BSEN 14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection:19.02.25

Expiry date:19.05.26

