

103 The Street, Adisham, Canterbury, Kent,
 CT33JP, England.
 07568487894
 castlecapers_bouncycastlerepairs@yahoo.com
 www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No	Size	Type	Make
CC0093	6m L x 4m W x 2.8m H	Jungle play zone	Airquee
Name and address of owner		1 st choice inflatables	
Manufacture date	Place of inspection	Name of inspector	
2018	1 st choice inflatables	Philippa miller	

Anchorage	Structure	Totally enclosed
How Many/type	Seams & stitching	Exits
Accessories	Blower length	Exit markings
Blower	Inside wall height	Independent support
Inlet, outlet mesh	Fall off height	Deflation
Cable and socket	Step/ramp	Emergency lighting
Impeller & flap	Entrapment	Slides
1.5hp	Trough depth	Platform height
PAT test	Grounding	Platform wall
Material	Sharp angles	1 st M wall
Fabric FR/strength	Stability	Slope remainder
Zips	Pressure	Climb
Thread	deflation	Run out
Rope	Air loss	End
Netting	Markings	Slip sheet
Windows	Identifications	Climb sheet
Artwork	Walls & towers	Run out length

All parts relevant to this unit have been inspected and found satisfactory unless listed below

How many users to height

1 M = 10	1.2 M = 8	1.5 M = 0	1.8 M = 0
----------	-----------	-----------	-----------

Risk assessment	Notes
Designated entrance and exit areas should be adhered to at all times. This safety certificate is for the inflatable only.	Max height = 1.2m Max users at this height = 8

I certify that the above equipment has been tested to BSEN 14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection: 02.03.26

Expiry date: 02.03.27

