103 The Street, Adisham, Canterbury, Kent,

CT33JP, England.

07568487894

castlecapers_bouncycastlerepairs@yahoo.com

www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No		Size	Туре		Make
CC0369	7.4m L	x 2.8m W x 2.6m H	Jungle Fun Ru	ın	Better Bounce
Name and address of owr	ner		1 st Choice	Inflatables	
Name and address of operator		1 st Choice Inflatables			
Manufacture date		Place of i	nspection		Name of inspector
2018		1 st choice	inflatables		Louise Reade

Seams & stitching	Exits
Blower length	Exit markings
Inside wall height	Independent support
Fall off height	Deflation
Step/ramp	Emergency lighting
Entrapment	Slides
Trough depth	Platform height
Grounding	Platform wall
Sharp angles	1 st M wall
Stability	Slope remainder
Pressure	Climb
deflation	Run out
Air loss	End
Markings	Slip sheet
Identifications	Climb sheet
Walls & towers	Run out length
t have been inspected and f	ound satisfactory unless listed
below	
	Blower length Inside wall height Fall off height Step/ramp Entrapment Trough depth Grounding Sharp angles Stability Pressure deflation Air loss Markings Identifications Walls & towers thave been inspected and for

_		r	r	
	1 M = 4	1.2 M = 4	1.5 M = 4	1.8 M = 4
			2.0	210111

Risk assessment	Notes	
This safety certificate is for the inflatable only. Designated	Max height = 1.8m	
entrance and exit areas should be adhered to at all times.	Max users at this height = 4	

I certify that the above equipment has been tested as indicated to BSEN14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection: 29.01.25

Expiry date: 29.01.26

